

OCT 02 2018

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-29172
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 232

2. Surface Location

UL - Lot K	Section 19	Township 18-S	Range 38-E	Feet from 2501	N/S Line SOUTH	Feet From 1410	E/W Line WEST	County LEA
---------------	---------------	------------------	---------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN no	PRODUCING Inj	DATE 9/17/18
-------------	---------------	------------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	-0-	-0-	N/A	-30-	1034
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

5 sec Blowdown - 5 sec Blowdown - 5 sec Blowdown

Danny Lane 575-318-1959 DL

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test <i>[Signature]</i>
E-mail Address: mendy_johnson@oxy.com	
Date: SEP 26 2018	
Phone: 806-592-6280	
Witness:	