

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

OCT 03 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-35742
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. 244

7. Surface Location

UL - Lot E	Section 34	Township 18-S	Range 38-E	Feet from 2246	N/S Line NORTH	Feet From 597	E/W Line WEST	County LEA
---------------	---------------	------------------	---------------	-------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status	SHUT-IN T/A	PRODUCING	DATE 13 Aug 18
-------------	----------------	-----------	-------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0	N/R	N/R	10	10
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME WTR. GAS. CO2

A-) No Puff to Nothing
B-) No Rise
C-) No Rise
D-) Puff to Nothing
2 (2) oily water

Daniel G. Lora

575-318-5067

Signature: <u>Mendy Johnson</u>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: <u>mendy_johnson@oxy.com</u>	
Date: <u>SEP 26 2018</u>	
Phone: 806-592-6280	
Witness:	