

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

HOBBS OCD

OCT 02 2018

BRADENHEAD TEST REPORT

RECEIVED  
30-025-42478

Operator Name OCCIDENTAL PERMIAN, LTD	Well No. 952
Property Name NORTH HOBBS (G/SA) UNIT	

7. Surface Location

UL - Lot O	Section 18	Township 18-S	Range 38-E	Feet from 828	N/S Line SOUTH	Feet From 2299	E/W Line EAST	County LEA
---------------	---------------	------------------	---------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status Inj	SHUT-IN	PRODUCING	DATE 9/13/18
--------------------	---------	-----------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	-0-	N/A	N/A	4	1020
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Danny Lane 575-318-1159 DL

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: SEP 26 2018	
Phone: 806-592-6280	
Witness:	