

HOBBS OCD

OCT 03 2018

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PREMIER LTD		API Number 30-025-42776
Property Name NORTH HOBBS UNIT (G/SA)		Well No. 959

7. Surface Location

UL - Lot 0	Section 18	Township 18S	Range 38E	Feet from 948	N/S Line S	Feet From 2299	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR NO	SWD NO	OIL NO	PRODUCER NO	GAS NO	DATE 9/13/18
-------------------------	----------------------	-----------------------	------------------	------------------	-----------------------	------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	-0-	N/A	N/A	-0-	910
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

1502
BLOW
DOWN

3502
BLOW
DOWN

KRIS ALLEN 575-318-4763

Signature: Mendy Johnson	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMIN. ASST.	Re-test
E-mail Address: Mendy-johnson@oily.com	
Date: SEP 26 2018	
Phone: 806-692-0280	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM