

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

OCT 05 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Kevin O. Butler		API Number 30-005-00658 ✓
Property Name S. Cap Rock Queen		Well No. #10 ✓

Surface Location

UL - Lot J	Section 30	Township 15S	Range 31E	Feet from 1980	N/S Line S	Feet From 1980	E/W Line E	County Chaves ✓
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	---------------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	OIL	PRODUCER	GAS	DATE 10-5-18 ✓
------------------	----	----------------	----	------------------------	-----	-----	----------	-----	--------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	0	N/A	0	500
Flow Characteristics					
Pull	Y / 0	Y / 0	Y / N	Y / 0	CO2 —
Steady Flow	Y / 0	Y / 0	Y / N	Y / 0	WTR — ✓
Surges	Y / 0	Y / 0	Y / N	Y / 0	GAS —
Down to nothing	Y / 0	Y / 0	Y / N	Y / 0	Type of Fluid
Gas or Oil	Y / 0	Y / 0	Y / N	Y / 0	Injected for
Water	Y / 0	Y / 0	Y / N	Y / 0	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: [Signature]		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title: 918-914-9357		Re-test
E-mail Address:		[Signature]
Date:	Phone:	
Witness: [Signature]		

INSTRUCTIONS ON BACK OF THIS FORM