

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

OCT 05 2018

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Kenn O Butler		API Number 30-005-01161	
Property Name S. CapRock Queen		Well No. #15	

1. Surface Location

UL - Lot 0	Section 28	Township 14S	Range 31E	Feet from 330	N/S Line S	Feet From 1920	E/W Line E	County Chaves
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	-------------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ INJ ☐ SWD	PRODUCER OIL ☐ GAS ☐	DATE 10-5-18
--	--	--	---	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	0	NA	0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid ☒
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for ☐
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if ☐

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: [Signature]		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title: 918-414-4317		Re-test [Signature]	
E-mail Address:			
Date:	Phone:		
Witness: Gary Robinson			

INSTRUCTIONS ON BACK OF THIS FORM