

HOBBS OCD

OCT 03 2018

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-20047
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. 91

7. Surface Location

UL - Lot P	Section 9	Township 19-S	Range 38-E	Feet from 990	N/S Line SOUTH	Feet From 330	E/W Line EAST	County LEA
---------------	--------------	------------------	---------------	------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status	SHUT-IN T/A	PRODUCING	DATE 17 July 18
-------------	----------------	-----------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	N/A	N/A	N/A	0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	Y / N
Steady Flow	Y / N	Y / N	Y / N	Y / N	Y / N
Surges	Y / N	Y / N	Y / N	Y / N	Y / N
Down to nothing	Y / N	Y / N	Y / N	Y / N	Y / N
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Y / N
Water	Y / N	Y / N	Y / N	Y / N	Y / N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

A) No Rise
B) No Rise
C) No Rise
D) Small puff to nothing
Less than 1 gal oil/water

Daniel Calvert
575-318-5067

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: SEP 26 2018	
Phone: 806-592-6280	
Witness:	