

HOBBS OCD

OCT 03 2018

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OXY	APT Number 30-025-07361
Property Name North Hobbs (G/SA) unit	Well No. 131A

7. Surface Location

UL - Lot -L	Section 14	Township 18-S	Range 38-E	Feet from 2310	N/S Line South	Feet From 330	E/W Line West	County Lea
-----------------------	----------------------	-------------------------	----------------------	--------------------------	--------------------------	-------------------------	-------------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ	PRODUCER OIL ☒ GAS ☐	DATE 9/14/18
--	--	------------------------	--	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	-0-	-0-	N/A	-6-	1496
Flow Characteristics					
Puff	Y / ☒ N	☒ Y / N	Y / N	☒ Y / N	CO2 ☐
Steady Flow	Y / ☒ N	☒ Y / N	Y / N	☒ Y / N	WTR ☐
Surges	Y / ☒ N	☒ Y / N	Y / N	☒ Y / N	GAS ☒
Down to nothing	☒ Y / N	☒ Y / N	Y / N	☒ Y / N	Type of Fluid
Gas or Oil	Y / ☒ N	☒ Y / N	Y / N	☒ Y / N	Injected for
Water	Y / ☒ N	☒ Y / N	Y / N	☒ Y / N	Waterflood if

Remarks - Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

.5 Sec
Blow down

2 sec
Blow down

10 sec
Blow down

Danny June 575-318-1959 DL

Signature: Mendy Johnson	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMIN ASSOC	Re-test
E-mail Address: Mendy-johnson@oxy.com	gmj
Date: SEP 26 2018	
Phone: 806-592-16280	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM