

OCT 03 2018

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-35305
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. 242

7. Surface Location

UL - Lot A	Section 5	Township 19-S	Range 38-E	Feet from 1556	N/S Line NORTH	Feet From 1102	E/W Line EAST	County LEA
---------------	--------------	------------------	---------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status -	SHUT-IN T/A.	PRODUCING	DATE 06 Aug 18
------------------	-----------------	-----------	-------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure -	0	N/R	N/R	0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

A.) No Puff to Nothing -
B.) No Rise -
C.) No Rise -
D.) No Puff to Nothing -

Daniel Colon

575-318-5067

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: SEP 26 2018	
Phone: 806-592-6280	
Witness:	