

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS

OCT 09 2018

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RE

BRADENHEAD TEST REPORT

36217

Operator Name EOG RESOURCES	API Number 3002532570000
Property Name RED HILLS NORTH UNIT	Well No. #710

7. Surface Location

UL - Lot 7	Section 7	Township 25S	Range 34E	Feet from 990	N/S Line FSL	Feet From 990	E/W Line FWL	Count LEA
---------------	--------------	-----------------	--------------	------------------	-----------------	------------------	-----------------	--------------

Well Status 1603 2 1832 LE

Well Status	SHUT-IN YES	PRODUCING 1/A	DATE 7/18/2018
-------------	----------------	------------------	-------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If Braden head flowed water, check all of the descriptions that apply:

	(A)Surf- Inter	(B)Intern(1)- Inter(2)	(C)Inter-Prod	(D)Prod Casing	(E)Tubing
Pressure	0	—	0	5 PSI	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	Y / N
Steady Flow	Y / N	Y / N	Y / N	Y / N	Y / N
Surges	Y / N	Y / N	Y / N	Y / N	Y / N
Down to nothing	Y / N	Y / N	Y / N	Y / N	Y / N
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Y / N
Water	Y / N	Y / N	Y / N	Y / N	Y / N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: (C) NO PRESSURE

(D) HAD 5 PSI BLEED OFF 1 MINUTE

BLEED OFF TO 0 PSI SOME FLUIDS CAME OUT OF 2" VALVE LESS THEN 2 GALLONS. WELL STATE IS CURRENTLY TA'D

gms

gms