

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

OCT 10 2018

BRADENHEAD TEST REPORT

Operator Name BC OPERATING	RECEIVED 30-025-23708-
Property Name Government E	Well No. 1

7. Surface Location

UL - Lot 1N	Section 25	Township 19S	Range 34E	Feet from 610	N/S Line S	Feet From 1880	E/W Line W	County Lea
-----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

YES ☒ TA'D WELL	NO ☐ SHUT-IN	YES ☐ INJ	NO ☒ INJECTOR	YES ☐ PRODUCER	NO ☒ GAS	DATE 10/10/18
---	-------------------------------------	----------------------------------	---	---------------------------------------	--	-------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	10	—	—	10	950
Flow Characteristics					
Puff	Y/N Y	Y/N Y	Y/N Y	Y/N Y	CO2 —
Steady Flow	Y/N Y	Y/N Y	Y/N Y	Y/N Y	WTR —
Surges	Y/N Y	Y/N Y	Y/N Y	Y/N Y	GAS —
Down to nothing	Y/N Y	Y/N Y	Y/N Y	Y/N Y	Type of Fluid
Gas or Oil	Y/N Y	Y/N Y	Y/N Y	Y/N Y	Injected for
Water	Y/N Y	Y/N Y	Y/N Y	Y/N Y	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

SURFACE VALVE needs TO Be Replaced - Immediately
GEORGE BOWER - Compliance Supervisor
575-399-2990

Signature: Tommy Brown	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test MB
E-mail Address:	
Date: 10/10/18	Phone:
Witness: Tommy Brown	

INSTRUCTIONS ON BACK OF THIS FORM