

HOBBS CCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

OCT 12 2018

BRADENHEAD TEST REPORT

RECEIVED

Operator Name TLT SWI	API Number 30-025-31443 ✓
Property Name LOST TANK SWD	Well No. #1 ✓

2. Surface Location

UL - Lot E	Section 31	Township 21S	Range 32E	Feet from 1980	N/S Line N	Feet From 660	E/W Line W	County LEA ✓
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	------------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ SWD	OIL SWD	PRODUCER GAS	DATE 10-12-18 ✓
------------------	-----------	----------------	-----------	-------------------	-------------------	-----------------	---------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	450
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR — ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS — ✓
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test [Signature]
E-mail Address:	
Date:	Phone:
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM