

OCT 22 2018

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-26115
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. 120

7. Surface Location

U/L - Lot C	Section 5	Township 19-S	Range 38-E	Feet from 1272	N/S Line NORTH	Feet From 1420	E/W Line WEST	County LEA
----------------	--------------	------------------	---------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status <input checked="" type="checkbox"/>	SHUT-IN	PRODUCING	DATE 13 Aug 18	<i>Injection</i>
--	---------	-----------	-------------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	N/R	N/R	N/R	0	962
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME WTR, GAS, CO2

A.) No Rise -
 B.) No Rise -
 C.) No Rise -
 D.) No Prod & Nothing

Daniel Glon
575-318-5067

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test <i>JMB</i>
E-mail Address: mendy_johnson@oxy.com	
Date: 10/15/18	Phone: 806-592-6280
Witness:	