

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

OCT 22 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OXY	API Number 30-025-43841
Property Name North Hobbs (GSA) unit	Well No. 657

Surface Location

UL - Lot B	Section 24	Township 18S	Range 37E	Feet from 160	N/S Line N	Feet From 2269	E/W Line ←	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO ☒	SHUT-IN YES ☒ NO ☒	INJECTOR ☒	SWD	OIL	PRODUCER	GAS	DATE 10/2/18
---	---	---	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	-0-	N/A	N/A	-0-	1449
Flow Characteristics					
Puff	☒ Y ☒ N	Y / N	Y / N	Y / ☒ N	CO2 ☐
Steady Flow	☒ Y ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☐
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS ☒
Down to nothing	☒ Y ☒ N	Y / N	Y / N	☒ Y ☒ N	Type of Fluid Injected for
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	Waterflood if applies.
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks -- Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies

**5 sec
Blow down**

**.5 sec
Blow down**

Danny lane 575-316-1959 OL

Signature: Mendy Johnson	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMIN ASSOCIATE	Re-test
E-mail Address: MENDY JOHNSON @ OXY.COM	
Date: OCT 16 2018	
Phone: 806-542-6280	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM