District I 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

OCT 2 2 2018

BRADENHEAD TEST REPORT									RECEIVED			
Operator Name OCCIDENTAL PERMIAN, LTD									30-025-23081			
Property Name NORTH HOBBS (G/SA) UNIT									Well No. 421			
<u> </u>				^{7.} Su	ırface Loca	ation				<u> </u>		
1 ~ 1		Township 18-S	· •		Feet from	N/	N/S Line Feet NORTH 7			E/W Line EAST	County LEA	
	J.			V	Vell Statı	us		<u> </u>				
Well	Status		SHUT-IN		PRODUCING		10(2/19					
	OPE	N BRADEN	HEAD AND IN	TERMEDIATE T			IVIDUALI	LY FOR 15	MINUTI	ES EACH		
If bradenhead	flowed wat	ter, check all	of the descripti	Ons that apply:	ERVED D	ATA						
	\	(A)Sı	ırf-Interm	(B)Interm(1)-I	nterm(2)	(C)Interm-Prod			(D)Prod Csng		(E)Tubing	
	Pressure Flow Characteristics		-6-	-0.	-	^	1/4		4	50	600 -	
Puff			(A) N				Y/N		Y/N		-	
Steady F	low	— 	Y/ N	Y	Y/ (Y)		Y / N		Y/N		-	
Surges			Y / (S)	Y /	Y / N)		Y / N		Y / N		†	
Down to nothing			(Y)/N	(Y)	(Y) N		Y/N		Y/N			
Gas or Oil Water			Y / (N) Y / (N)		Y / N)		Y / N Y / N		Y / N Y / N			
			1	<u> </u>	· · ·				L			
If bradenhead flowed water, check all of the descriptions that apply: CLEAR FRESH SALTY							SULFUR BLACK					
—————				SALIT			SOLION					
Remarks:						INJEC	TING AT	THISTIN	ИЕV	WTR,GA	S,CO2	
		6	2 sec Blowdow		1) Sec	ı						
			5 low dow) Sec Blowo	lown						
				Dann	y Lan	·e 5	575-	318-	1959	D2		
									`	<u>-</u>	- 10 mm	
Signature: Mendy Johnson									OIL CONSERVATION DIVISION			
1 1 1 1									Entered into RBDMS			
Title: ADMINISTRATIVE ASSOCIATE									Re-test			
E-mail Address: mendy_johnson@oxy.com									(MW			
Date: 1 6 2018 Phone: 806-592-6280												

Witness: