

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

APACHE Corp		Operator Name	30-025-40849
North East Drinkard Unit			Well No. 263

7. Surface Location

UL - Lot C	Section 3	Township 21-S	Range 37-E	Feet from 3345	N/S Line N	Feet From 1620	E/W Line W	County LEA
---------------	--------------	------------------	---------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D Well YES ☒	SHUT-IN YES ☒	INJECTOR ☒	PRODUCER OIL ☒	DATE 10-31-18
---	---	--	--	------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	—	—	0	0
Flow Characteristics					NOT INS
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

MIT/BHT -
Parker Services
Ser# 5162
Cal 7/9/18

Signature:		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date: 10-31-18	Phone:	
Witness: Kerry Fortner - OCD		

399-3221