## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CIDENTAL PERMIAN, LTD  Property Name NORTH HOBBS (G/SA) UNIT								1 No. 42
	be			7. Surface l	Location			
JL - Lot	Section	Township	Range	Feet	from N/S Line	Feet From	E/W Line	County
0	18	18-S	38-E	3	30 SOUTH	2310	EAST	LEA
				Well S	tatus			
Well Status			SHUT-IN	PROD	UCING	DATE		
			No			10-02-18		_

If bradenhead flowed water, check all of the descriptions that apply:

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	(t)	68	NA	Ø	1020
Flow Characteristics					
Puff	(Ø) N	Ø / N	Y/ N	<b>②</b> / N	
Steady Flow	V/(S)	Y/69	Y/N	Y / 🚫	
Surges	Y / 🕸	Y / 169	Y / N	V / 🔊	
Down to nothing	Ø/ Ŋ	Ø/N	Y / N	Ø/ N	
Gas or Oil	V/(S)	Y / 80	Y/N	Y / 🐒	
Water	Y / (N)	Y / 🔊	Y/N	Y/(\$)/	

Y SULFUR	BLACK
INJECTING AT THIS T	TIMEWTR,GAS,CO2
_	

Shawn marsland 254-423-5440 Shawn & marsland & oxy. com

Signature: Mandy Johnson	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test /
E-mail Address: mendy_johnson@oxy.com	$\chi$ 1
Date: (1/ 2.5 2018 Phone: 806-592-6280	
Witness:	