

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD		API Number 30-025-28346
Property Name SOUTH HOBBS (G/SA) UNIT		Well No. 143

7. Surface Location

UL - Lot P	Section 4	Township 19-S	Range 38-E	Feet from 1160	N/S Line SOUTH	Feet From 33	E/W Line EAST	County LEA
---------------	--------------	------------------	---------------	-------------------	-------------------	-----------------	------------------	---------------

Well Status

330

Well Status	SHUT-IN T/A	PRODUCING	DATE 10/24/18
-------------	----------------	-----------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	N/R	N/R	N/R	0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	Y / N
Steady Flow	Y / N	Y / N	Y / N	Y / N	Y / N
Surges	Y / N	Y / N	Y / N	Y / N	Y / N
Down to nothing	Y / N	Y / N	Y / N	Y / N	Y / N
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Y / N
Water	Y / N	Y / N	Y / N	Y / N	Y / N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

D.) No Rise-
B.) No Rise-
C.) No Rise-
D.) No Rise to water,

Daniel / Colvin

575-318-5067

Signature: <i>Mendy Johnson</i>		OIL CONSERVATION DIVISION	
Printed name: MENDY JOHNSON		Entered into RBDMS	
Title: ADMINISTRATIVE ASSOCIATE		Re-test	
E-mail Address: mendy_johnson@oxy.com			
Date: OCT 24 2018	Phone: 806-592-6280		
Witness:			