

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-29756
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. 218

7. Surface Location

UL - Lot A	Section 4	Township 19-S	Range 38-E	Feet from 652	N/S Line NORTH	Feet From 563	E/W Line EAST	County LEA
---------------	--------------	------------------	---------------	------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 10 Aug 18	14 injector
-------------	---------	-----------	-------------------	-------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Csg	(E) Tubing
Pressure	0	N/R	N/R	10	10.42
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

A.) No Polt & Nothing
B.) No Rise
C.) No Rise
D.) Small Polt to Nothing

Daniel Colon
575-318-5067

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test <i>77</i>
E-mail Address: mendy_johnson@oxy.com	
Date: OCT 24 2018	
Phone: 806-592-6280	
Witness:	