

NOV 05 2018
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-05440
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 121

7. Surface Location

UL - Lot E	Section 13	Township 18-S	Range 37-E	Feet from 1980	N/S Line NORTH	Feet From 660	E/W Line WEST	County LEA
---------------	---------------	------------------	---------------	-------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status —	SHUT-IN T/A	PRODUCING T/A	DATE 10-19-18
------------------	----------------	------------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	Ø	N/A	N/A	70	70
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

(A) Had nothing on it.

(D) Had 70 Pounds on TBless Bled to Ø in 35 seconds.

Bryan Loftin
575-441-9739
Bryan.Loftin@oxy.com

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: NOV 25 2018	Phone: 806-592-6280
Witness:	