State of New Mexico

State of New Mexico

State of New Mexico

Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Mario Camuner (575) 964 -4232 API Number 30-025-35758 Property Name NORTH HOBBS (G/SA) UNIT Well No. 7 Surface Location UL - Lot Section Township Range Feet from N/S Line E/W Line Feet From County 38-E 2188 SOUTH K 33 18-S 2510 WEST LEA Well Status PRODUCING Well Status DATE OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH **OBSERVED DATA** If bradenhead flowed water, check all of the descriptions that apply: (A)Surf-Interm (B)Interm(1)-Interm(2) (C)Interm-Prod (D)Prod Csng (E)Tubing Pressure 379 Flow Characteristics **(Ý)**/ N Puff Y 7 N Y 7 N Y / NSteady Flow Y / (3) Y/NY / N Y/NY / N Y/NSurges YIN Y / NDown to nothing **(Y)**/ N Y/NY/NY/NY / 🚫 Gas or Oil V / N V/N Y/NWater Y / N Y/NY / N If bradenhead flowed water, check all of the descriptions that apply: CLEAR FRESH SALTY SULFUR BLACK INJECTING AT THIS TIME / WTR. GAS. Remarks: sec Jown Mario Camunez 575-964-9232 Signature: OIL CONSERVATION DIVISION Printed name: MENDY JOHNSON Entered into RBDMS Title: ADMINISTRATIVE ASSOCIATE Re-test

E-mail Address: mendy johnson@oxy.com 2 5 2018

Phone: 806-592-6280

Witness:

OCT.