

HOBBS OCD

NOV 05 2018

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name	API Number
Property Name	Well No.
North Hobbs (G/SA) unit	654

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
H	23	18S	37E	1541	N	1273	E	

Well Status

TA'D WELL	YES	NO	SHUT-IN	YES	NO	INJ	INJECTOR	SWD	PRODUCER	OIL	GAS	DATE
												10/15/18

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	-0-	N/A	N/A	-0-	1379
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid injected for waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks -- Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

5 Sec
Blowdown

2 Sec
Blowdown

Danny lane 575-318-1954 DL

Signature: MENDY JOHNSON	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMIN. ASSOCIATE	Re-test
E-mail Address: MENDY-JOHNSON@OXY.COM	
Date: OCT 25 2018	
Phone: 806-592-6280	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM