Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WFLL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISIONS	
<u>District III</u> – (505) 334-6178	1220 South St. Francis O.	5. Maleate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460		3 718 STATE FEE X 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505 NOV 1.5	o. State on & oas Dease No.
87505		
(DO NOT USE THIS FORM FOR PROPO	ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLIE	CATION FOR PERMIT" (FORM C-101) FOR SUCH	Eunice Monument South Unit B
PROPOSALS.)	_	8. Well Number 850
1. Type of Well: Oil Well	Gas Well Other	
2. Name of Operator XTO ENERGY, INC.		9. OGRID Number 005380
3. Address of Operator		10. Pool name or Wildcat
6401 HOLIDAY HILL ROAD MID	AND TEXAS 79707	Eunice Monument; Grayburg-SA
4. Well Location		
Unit Letter B :	330 feet from the NORTH line and	1650 feet from the EAST line
Section 11	Township 20S Range 36E	
Section 11	11. Elevation (Show whether DR, RKB, RT, GR, e	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
	Tr. Dievation (Snow whether DR, 100), R1, OR, e	
Commission of the Commission o	<u> </u>	
12 Check A	Appropriate Box to Indicate Nature of Notic	e Report or Other Data
12. Check 7	rppropriate box to indicate readure of reode	c, report of Other Data
NOTICE OF IN	TENTION TO: SL	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WO	ORK ALTERING CASING
TEMPORARILY ABANDON	1	ORILLING OPNS.□ P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	ENT JOB PNR
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM		<u> </u>
OTHER:	OTHER:	
	leted operations. (Clearly state all pertinent details,	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
* *	•	
		PA approval SDON NO venting HSM. MIRU (Keyy Energy 399
	ooler POH/w tog disassemble & LD Esp rd Spooler SWI SL s RD TT. RU PA equip (advises Mark Whitaker/w NMOCD	OON No venting HSM. RU Empire TT RIH/w 114 jts 2-7/8" tbg
	Circ well/w 60 bbls FW no circ spot 30 sks class C cmt/w 29	
10/20-10/22/2018: SHUT DOWN FOR THE WEEKEND.		
10/22-10/24/2018No ventitng HSM. RIH did not tag cmt pulled Tbg to 3300' spot 60 sks class C/w 2% CACL 2 POH/w 25 stds WOC 4 hrs RIH to 3604'		
no tag pull up to 3300' spot 150 sks class C cmt SWI SDOW CMIC Fabian Aranda. RIH tag TOC @2369' (est.CMT 3779' to 2369') circ 50bbls psi test csg		
to 500psi no test LD 30 jts POH/w 22stds. RIH/w PKR and set @1484' test csg to 1000psi test good rls pkr POH RIH opened ended circ 10 bbls BW ahead mix 10 sks gel/w 40 bbls BW spot 30sks class C 2369'-2189' POH/w 25 stds SWI. RIH tag TOC @2183' POH/w 26 stds LD 17jts perf @1600'		
		@325psi squeeze 70 sks class c/w 2% calc2 1600'-1425' WOC
	ed tag TOC 1421' POH SWI SDON.	@323p3i 3queeze 70 5k5 class c/ w 2/6 caic2 1000 -1423 WOC
·	Approved	for Plugging of wellbore only. Liability
See additional page for rest		d is retained pending restoration and
	completion	of the C-103, Specific for Subsequent
Spud Date:		Well Plugging, which may be found on
	Restoration	eb page under forms. n Due By <u>10-27-2019</u>
I hereby certify that the information	above is true and complete to the best of my knowled	ruge and benet.
	A = 0	And the second s
471 111	Amol OX	D 4 mp 44/07/0040
SIGNATURE (LACE)	NTLE Regulatory Analyst	DATE 11/07/2018
Type or print name Patricia Donald	patricia_donald@xtoenerg E-mail address:	y.com PHONE.4325718220
For State Use Only	E-iliali auditss:	FRONE, OLD FOLLO
201 State Cost Only	VII.	1 1 -
APPROVED BY: Vlall	Witcher TITLE P.E.S.	DATE 11/13/2018
Conditions of Approval (if any):		

10/24 10/27 2018: No venting HSM. Ru WL perf @745' hut pressure bleed down POH RD WL RIH/w pkr set @40'. Attempt to get injection rate pressure up to the 1000psi bleed down rls pkr POH. Rd work floor dig out cellar/w backhoe to check for risers. RDWSU to deepen cellar SWI SDON. Fill out confined space permit cont digging out wellhead to 14' pulled surface riser found plugged off unplugged. Talked to Mark Whitaker/w NMOCD about spotting across perfs. Refill & pack cellar RUWSU PU 25 jts spot 30 sks class c 765'-615' POH/w 10stds SWI SDON.RIH tag TOC 616' LD 20 jts RU WL perf @300' rd WL set pkr @40' establish injection rate 2bpm @400psi start circ around WH. Circ 280 sks class C cmt 300' to surface rls pkr POH top off well with cmt RDMO WB PA'd.