

State of New Mexico
Energy, Minerals and Natural Resources Department
HOBBS OCOil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

NOV 05 2018 RECEIVED	Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-28304
Property Name SOUTH HOBBS (G/SA) UNIT		Well No. COOP 1

7. Surface Location

UL - Lot B	Section 6	Township 19-S	Range 38-E	Feet from 200	N/S Line NORTH	Feet From 1380	E/W Line EAST	County LEA
---------------	--------------	------------------	---------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN ✓ T/A	PRODUCING	DATE 10/24/18	
-------------	------------------	-----------	------------------	--

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	0	N/R	N/R	10 psi	-10-
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

well is T/A

A.) 0psi - No Puff Bleed to Nothing

B.) No Rise

C.) No Rise

D.) 10psi - Small puff to Nothing

Daniel Colvin
575.318.5067

Signature: <i>Mendy Johnson</i> Printed name: MENDY JOHNSON Title: ADMINISTRATIVE ASSOCIATE E-mail Address: mendy_johnson@oxy.com Date: OCT 24 2018 Phone: 806-592-6280 Witness:	OIL CONSERVATION DIVISION Entered into RBDMS Re-test <i>[Signature]</i>
--	--