District I

M

32

1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico Energy, Minerals and Natural Resources

10885 05218	Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office BRADENHEAD TEST REPORT		
- And Wall	Operator Name CCIDENTAL PERMIAN, LTD		
	Property Name		

Operator Name OCCIDENTAL PERMIAN, LTD							3 API Numbe 30-025-2826			
Property Name NORTH HOBBS (G/SA) UNIT							W	'ell No. 142		
7. Surface Location										
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County	

Well Status

610

Well Status	SHUT-IN	PRODUCING	DATE	
			10-19-18	INT

SOUTH

WEST

LEA

1210

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

18-S

38-E

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	Ø	NA	NA	10	1080
Flow Characteristics					
Puff	Y / 🔇	Y/N	Y/N	⊘ / N	
Steady Flow	Y/®	Y/N	Y / N	Y / 🔇	
Surges	Y/®	Y/N	Y/N	Y / 🔞	
Down to nothing	Ø/ N	Y/N	Y/N	Ø 7 N	
Gas or Oil	Y / 🛇	Y/N	Y/N	Y / 📎	
Water	Y/®	Y/N	Y/N	Y / 🔞	

If bradenhead flo	wed water, check all of the descripti	ons that apply:		
CLEAR	FRESH	SALTY	SULFUR	BLACK

	·			
ı	<u></u>	 	— ———— ———————————————————————————————	L
			•	
1	Remarks:	INJEC	TING AT THIS TIME V WT	R. GAS. CO2

D: 25EC TO 8

Tindy Lac Lows 575-390-7214

Signature: Mendy	Johnson	OIL CONSERVATION DIVISION		
Printed name: MENDY JOHNSON		Entered into RBDMS		
Title: ADMINISTRATIVE ASSOCI	ATE	Re-test		
E-mail Address: mendy_johnson@ox	xy.com			
Date: 0CT 2 5 2018	Phone: 806-592-6280	V		
	Witness:			