

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

NOV 13 2018

BRADENHEAD TEST REPORT

RECEIVED

Operator Name MESQUITE SWD		API Number 30-025-40813 ✓
Property Name PADUCA Fed. SWD		Well No. #2 ✓

1. Surface Location

UL - Lot 0	Section 22	Township 25S	Range 32E	Feet from 500	N/S Line S	Feet From 2000	E/W Line E	County LEA ✓
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	------------------------


Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWD ☒	PRODUCER OIL ☐ GAS ☐	DATE 11-13-18 ✓
--	--	--	---	---------------------------

OBSERVED DATA

	(A) Surface	(B) Interm1	(C) Interm2	(D) Prod Csg	(E) Tubing
Pressure	0	0	NA	0	850 ✓
Flow Characteristics					
Pull	Y/O	Y/O	Y/N	O/N	CO2 ☐
Steady Flow	Y/O	Y/O	Y/N	Y/O	WTR ☒
Surges	Y/O	Y/O	Y/N	Y/O	GAS ☐
Down to nothing	O/N	O/N	Y/N	O/N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/O	Y/O	Y/N	Y/O	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Rusty Parker	Entered into RBDMS
Title:	Re-test 
E-mail Address:	
Date:	Phone:
Witness: Davey Robinson	

INSTRUCTIONS ON BACK OF THIS FORM