

HOBBS OCD

NOV 05 2018

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-07667
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. 72

7. Surface Location

UL - Lot F	Section 9	Township 19-S	Range 38-E	Feet from 1650	N/S Line NORTH	Feet From 2310	E/W Line WEST	County LEA
---------------	--------------	------------------	---------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN T/A	PRODUCING	DATE 12/1/18
-------------	----------------	-----------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	4	N/R	N/R	5	5
Flow Characteristics					
Puff	(Y) N	Y / N	Y / N	(Y) N	
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	
Surges	Y / (N)	Y / N	Y / N	Y / (N)	
Down to nothing	(Y) N	Y / N	Y / N	(Y) N	
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

A.) Puff to Nothing
B.) No Rise
C.) No Rise
D.) Puff to Nothing

Daniel Colvin
575-318-5067

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test <i>X</i>
E-mail Address: mendy_johnson@oxy.com	
Date: OCT 24 2018	
Phone: 806-592-6280	
Witness:	