

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

NOV 05 2018

BRADENHEAD TEST REPORT

RECEIVED	Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-28982
	Property Name SOUTH HOBBS (G/SA) UNIT	Well No. 188

7. Surface Location

UL - Lot K	Section 5	Township 19-S	Range 38-E	Feet from 1493	N/S Line SOUTH	Feet From 1802	E/W Line WEST	County LEA
---------------	--------------	------------------	---------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN L	PRODUCING	DATE 22/10/18	Injector
-------------	--------------	-----------	------------------	----------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	N/R	N/R	0	1499
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☐ WTR, ☒ GAS, ☒ CO2

A) No Puff to Notice
B) No Rise
C) No Rise
D) No Puff to Notice
well is not injecting at this time

Daniel Colon

575-318-5067

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: OCT 24 2018	
Phone: 806-592-6280	
Witness:	