

7000 RCE East side

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OXY USA INC	API Number 30-025-07486
Property Name STATE LAND SECTION 30	Well No. 8

7. Surface Location

UL - Lot L	Section 30	Township 18-S	Range 38-E	Feet from 1980	N/S Line SOUTH	Feet From 1660	E/W Line WEST	County LEA
---------------	---------------	------------------	---------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN 7/11 ✓	PRODUCING 2	DATE 23 Oct 10
-------------	-------------------	----------------	-------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	U	N/A	N/A	5	5
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR. ___ GAS, ___ CO2

- A) No Puff to 10' 6" 1/2
B) No Rise
C) No Rise
D) Small Puff to 10' 6" 1/2 Less than 1 gal oil/water
E) Small Puff to 10' 6" 1/2

David Colunga
575-311-5067

Signature: <u>Mendy Johnson</u>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: <u>mendy.johnson@oxy.com</u>	
Date: <u>OCT 25 2018</u>	Phone: 806-592-6280
Witness:	