

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
HOBBS OCD

BRADENHEAD TEST REPORT

NOV 05 2018
Operator Name: **OXY**
Property Name: **North Hobbs (GSA) unit**
API Number: **30-025-43580**
Well No.: **686**

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
L	24	18S	37E	2119	S	1308	W	Lea

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR SWD ☐ INJ ☒	PRODUCER OIL ☐ GAS ☐	DATE 10/1/18
--	--	--	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	-0-	N/A	N/A	-0-	1502
Flow Characteristics					
Puff	☒ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	CO2 ☐
Steady Flow	☒ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	☒ Y / ☐ N	WTR ☐
Surges	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☒ N	GAS ☒
Down to nothing	☒ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	☒ Y / ☐ N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☒ N	
Water	☐ Y / ☒ N	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

**5 Sec
Blowdown**

**3 min
Blowdown**

Danny Iune 575-316-1959 DL

Signature: Mendy Johnson	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMIN. ASSOCIATE	Re-test X
E-mail Address: MENDY_JOHNSON@OXY.COM	
Date: OCT 25 2018	
Phone: 806-592-6280	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM