District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Amerals and Natural Reso Of Conservation Division 20 South St. Francis Dr. Santa Fe, NM 87505 NOV 1 9 2018

Form C-129 Revised August 1, 2011

Submit one copy to appropriate District Office

NFO Permit No. (For Division Use Only)

APPLICATION FOR EXCEPTION TO NO-FLARE RULE 19.15.18.12 (See Rule 19.15.18.12 NMAC and Rule 19.15.7.37 NMAC)

| | A. | Applicant ConocoPhillips Company , | | | |
|---|---|--|-----------------------------------|--|--|
| | | whose address is P. O. Box 51810 Midland, TX 79710 | | | |
| | | hereby requests an exception to Rule 19.15.18.12 for days or until | | | |
| | Name of Lease Vacuum Abo Battery 3 Name of Pool | | | | |
| | | | | | |
| | | Location of Battery: Unit Letter | Section 34 Township 17S Range 35E | | |
| | | Number of wells producing into battery 23 | | | |
| B. Based upon oil production ofbarrels per day, the e | | barrels per day, the estimated * volume | | | |
| | | of gas to be flared is 7600 | MCF; Valueper day. | | |
| | C. Name and location of nearest gas gathering facility: | | | | |
| | | | | | |
| D. DistanceEstimated cost of connection | | ost of connection | | | |
| E. This exception is requested for the following reasons: | | | reasons: | | |
| | DCP line pressure | | | | |
| | | Attached is a list of wells. | 30.025-02888 | | |
| | | | | | |
| | | | | | |
| OPERATOR OIL CONSERVATION DIVISION | | | | | |
| I hereby certify that the rules and regulations of the Oil Conservation Division have been complied with and that the information given above Approved I Intil | | | | | |
| is true and complete to the best of my knowledge and belief. Approved Until | | | | | |
| Signature Show By Majeys Brown | | | | | |
| Printed Name | | | | | |
| & Title Rhonda Rogers Staff Regulatory Technician Title | | | | | |
| E-mail Address_rogerrs@conocophillips.com Date 11/19/2018 | | | | | |
| Date | Date 11/13/2018 Telephone No. (432)688-9174 | | | | |

Gas-Oil ratio test may be required to verify estimated gas volume.

Vac Abo Unit Battery 3

| VA 04-05 | 30-025-02888 |
|----------|--------------|
| VA 06-57 | 30-025-02990 |
| VA 06-67 | 30-025-08541 |
| VA 06-69 | 30-025-08542 |
| VA 06-70 | 30-025-08523 |
| VA 06-76 | 30-025-20200 |
| VA 06-80 | 30-025-20119 |
| VA 06-86 | 30-025-30760 |
| VA 08-10 | 30-025-03025 |
| VA 08-12 | 30-025-20058 |
| VA 10-06 | 30-025-03012 |
| VA 11-07 | 30-025-02993 |
| VA 13-02 | 30-025-03044 |
| VA 13-03 | 30-025-03045 |
| VA 13-05 | 30-025-03067 |
| VA 13-10 | 30-025-03070 |
| VA 13-11 | 30-025-03049 |
| VA 13-16 | 30-025-03072 |
| VA 13-21 | 30-025-37384 |
| VA 13-24 | 30-025-37431 |
| VA 14-02 | 30-025-03064 |
| VA 14-04 | 30-025-03066 |