

NOV 26 2018

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name BASIN ALLIANCE		API Number 30-025-28083	
Property Name STATE AT		Well No. #1	

Surface Location

UL - Lot G	Section 33	Township 18S	Range 36E	Feet from 2310	N/S Line N	Feet From 2310	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	YES	SHUT-IN NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 11-19-18
------------------	----	-----	---------------	-----	------------------------	-----	-----------------	-------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Cemented	N/A	N/A	0	VAC
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ☒
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	N / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

POST WORKOVER

Signature: Hugo Naegele Jr		OIL CONSERVATION DIVISION	
Printed name: Hugo Naegele Jr		Entered into RBDMS	
Title: Member		Re-test	
E-mail Address: Hnaegele55@bajabbb.com			
Date: 11-19-18	Phone: 575-392-5999		
Witness: Shay Robinson			

INSTRUCTIONS ON BACK OF THIS FORM