

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JAN 23 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Cross Timbers	API Number 30-025-38304
Property Name ENCORE 22 ST Com	Well No. #1

Surface Location

UL - Lot H	Section 22	Township 17S	Range 34E	Feet from 1730	N/S Line N	Feet From 1000	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status


TA'D WELL ☒ YES ☐ NO	SHUT-IN ☒ YES ☐ NO	INJ ☐ YES ☐ NO	INJECTOR ☐ YES ☐ NO	PRODUCER ☒ OIL ☐ GAS	DATE 1-23-19
--	--	---	--	--	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	NONE
Flow Characteristics					
Pull	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	CO2 ☐
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	WTR ☐
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	☒ Y / N	☒ Y / N	Y / N	☒ Y / N	Type of Fluid Injected for Water level if applies
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

T/A TEST

Signature: 	OIL CONSERVATION DIVISION
Printed name: KEVIN BENNETT	Entered into RBDMS
Title: LEASE OPERATOR	Re-test: 
E-mail Address: Kevin.Bennett@CTFieldsVCS.com	
Date: 1-23-19	Phone: 575-513-8156
Witness: Shay Robinson	

INSTRUCTIONS ON BACK OF THIS FORM