

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

FEB 26 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Mammoth		API Number 30-025-01923
Property Name LEA A ST		Well No. #4

Surface Location									
UL - Lot E	Section 8	Township 17S	Range 34E		Feet from 1650	N/S Line N	Feet From 330	E/W Line W	County LEA

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJ	INJECTOR SWD	☒ OIL	PRODUCER GAS	DATE 2-25-19
------------------	-------------------------------------	----------------	-------------------------------------	-----	-----------------	--------------------------------------	-----------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	NA	NA	10	10
Flow Characteristics					
Pull	Y / ☒ N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / ☒ N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	☒ Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / N	Injected for
Water	Y / ☒ N	Y / N	Y / N	Y / N	Waterflow if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Seal needs operator

Signature: Gay Foot	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test OK
E-mail Address:	
Date:	Phone:
Witness: Gay Plenson	

INSTRUCTIONS ON BACK OF THIS FORM