

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

FEB 26 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Mammoth		API Number 30-025-01977 ✓	
Property Name STATE X		Well No. #2 ✓	

Surface Location

UL Lot H	Section 7	Township 17S	Range 34E	Feet from 1650	N/S Line N	Feet From 330	E/W Line E	County LEA ✓
--------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	------------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJ	INJECTOR SWD ☒ OIL	PRODUCER GAS	DATE 2-25-19 ✓
--	--	-----	--	-----------------	--------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	25	25 ✓
Flow Characteristics					
Puff	☒ Y ☐ N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	☒ Y ☐ N	Y / N	Y / N	Y / N	WTR ☐
Surges	☒ Y ☐ N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	☒ Y ☐ N	Y / N	Y / N	Y / N	Type of fluid injected for waterflood if applies
Gas or Oil	☒ Y ☐ N	Y / N	Y / N	Y / N	
Water	☒ Y ☐ N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Syn reads 0 psia

Signature: Larry Rolinson		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test DR	
E-mail Address:			
Date:	Phone:		
Witness: Larry Rolinson			

INSTRUCTIONS ON BACK OF THIS FORM