

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

FEB 26 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Mammoth		API Number 30-025-23096 ✓	
Property Name LEA OR ST		Well No. #3 ✓	

Surface Location									
UL - Lot P	Section 12	Township 18S	Range 36E		Feet from 660	N/S Line S	Feet From 660	E/W Line E	County LEA ✓

Well Status						DATE		
TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJ	SWD	OIL OIL	GAS GAS	2-25-19 ✓

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	could not open	N/A	N/A	0	VAC ✓
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ☒
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☒
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Had to replace surf. csg valve before next gr. ✓

Signature: Aug. Nelson		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test JK	
E-mail Address:			
Date:	Phone:		
Witness: Aug. Nelson			

INSTRUCTIONS ON BACK OF THIS FORM