

FEB 26 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Mammoth		API Number 30-025-25477 ✓	
Property Name LEA A ST.		Well No. #6 ✓	

1. Surface Location

UL - Lot N	Section 8	Township 17S	Range 34E	Feet from 660	N/S Line S	Feet From 1980	E/W Line W	County LEA ✓
----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	------------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	OIL	PRODUCER GAS	DATE 2-26-19 ✓
------------------	-----------	----------------	-----------	-----------------	-----	------------	-----------------	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	10	10 ✓
Flow Characteristics					
Puff	Y N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y N	Y / N	Y / N	Y / N	
Water	Y N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Sign needs operator

✓

Signature: [Signature]		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test [Signature]	
E-mail Address:			
Date:	Phone:		
Witness: [Signature]			

INSTRUCTIONS ON BACK OF THIS FORM