

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

FEB 26 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Caprock Exploration	API Number 30-025-30223
Property Name MESCALERO A ST.	Well No. #1

7. Surface Location

UL - Lot E	Section 18	Township 17S	Range 34E	Feet from 1980	N/S Line N	Feet From 660	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWD ☐	PRODUCER OIL ☒ GAS ☐	DATE 2-25-19
--	--	---	--	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm 1	(C) Interm 2	(D) Prod Csg	(E) Tubing
Pressure	0	NA	NA	0	0
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☒
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid injected for waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test [Signature]
E-mail Address:	
Date:	Phone:
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM