

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

FEB 27 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Mammoth		API Number 30-025-11214	
Property Name Langlie MATTIX		Well No. #13	

1. Surface Location									
UL - Lot I	Section 23	Township 24S	Range 37E		Feet from 1650	N/S Line S	Feet From 990	E/W Line E	County LEA

Well Status								
TA'D WELL YES	NO	YES	SHUT-IN NO	INJ	SWD	OIL	PRODUCER GAS	DATE 2-27-19

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Field
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Well shut in
Prod. csg. valve is south valve

Signature: Les Jacob		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test JK	
E-mail Address:			
Date:	Phone:		
Witness: Greg Peterson			

INSTRUCTIONS ON BACK OF THIS FORM