

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>Burk Royalty</i>		API Number <i>30-025-02507</i> ✓	
Property Name <i>W. H. MILNER Fed.</i>		Well No. <i>#4</i> ✓	

Surface Location									
UL - Lot <i>C</i>	Section <i>35</i>	Township <i>20S</i>	Range <i>34E</i>		Feet from <i>990</i>	N/S Line <i>N</i>	Feet From <i>1650</i>	E/W Line <i>W</i>	County <i>LEA</i> ✓

Well Status								
TA'D WELL YES	☒ NO	☒ YES	SHUT-IN NO	INJ	INJECTOR ☒ SWD	PRODUCER OIL	GAS	DATE <i>3-1-19</i> ✓

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure					
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BHT was not done on this well. Well did not pass MIT in 2018 and has not been repaired.

2019 BHT - conceded Failure

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS <i>ML</i>	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness: <i>Greg Holman</i>			

INSTRUCTIONS ON BACK OF THIS FORM