

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

MAR 01 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Burk Property		API Number 30-025-02459 ✓	
Property Name CRUSES Fed.		Well No. #3 ✓	

7. Surface Location

UL - Lot N	Section 26	Township 20S	Range 34E	Feet from 330	N/S Line S	Feet From 1655	E/W Line W	County LEA ✓
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	------------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ INJ ☐ SWD	PRODUCER OIL ☐ GAS	DATE 3-1-19 ✓
--	--	--	---	-------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	950 ✓
Flow Characteristics					
Pull	Y / 0	Y / N	Y / N	Y / 0	CO2 ☐
Steady Flow	Y / 0	Y / N	Y / N	Y / 0	WTR ☒
Surges	Y / 0	Y / N	Y / N	Y / 0	GAS ☐
Down to nothing	0 / N	Y / N	Y / N	0 / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / 0	Y / N	Y / N	Y / 0	
Water	Y / 0	Y / N	Y / N	Y / 0	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Kurt Parker		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test HP	
E-mail Address:			
Date:	Phone:		
Witness: Ray Robinson			

INSTRUCTIONS ON BACK OF THIS FORM