State Of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham

Govenor

Sarah Cottrell Propst

Cabinet Secretary

Todd E. Leahy, JD, PhD

Deputy Cabinet Secretary

Gabriel Wade

Acting Division Director



"Response Required - Deadline Enclosed"

Field Inspection Program "Preserving the Integrity of Our Environment"

HOBBS OCD

18-Mar-19

MACK ENERGY CORP

P.O. Box 960 11344 Lovington Hwy Artesia, NM 88211-0960 MAR 1 9 2019

LETTER OF VIOLATION - Field Inspection

RECEIVED

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-025-08019] GRACE MITCHELL B FEDERAL #006

OGRID: 13837

J-05-17S-32E 1980 FSL 1980 FEL

Inspection Date

Type Inspection

Inspector

Corrective Action Due By

Inspection No.

3/15/2019

Routine Inspection

[LZR] Leslie Rickman

6/13/2019

iLZR197433598

Violations:

Rule

Violation

Comment

19.15.26 Injection Detection of Deficient Mechanical Integrity Communication downhole

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Hobbs OCD District Office

Ick Rickman

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

Oil Conservation Division * 1625 N. French Drive * Hobbs, NM 88240 Phone: 575-393-6161 * Fax: 575-393-0720 * www.emnrd.state.nm.us

Print

State Of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham

Govenor

Sarah Cottrell Propst

Cabinet Secretary

Todd E. Leahy, JD, PhD

Deputy Cabinet Secretary

Gabriel Wade

Acting Division Director



"Response Required - Deadline Enclosed"

Field Inspection Program "Preserving the Integrity of Our Environment"

18-Mar-19

MACK ENERGY CORP

P.O. Box 960 11344 Lovington Hwy Artesia, NM 88211-0960

Dear Operator:

LETTER OF VIOLATION - Field Inspection

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-025-08020] GRACE MITCHELL B FEDERAL #002

OGRID: 13837

P-05-17S-32E 660 FSL 660 FEL

Inspection Date

Type Inspection

Inspector

Corrective Action Due By

Inspection No.

3/15/2019

Routine Inspection

[LZR] Leslie Rickman

6/13/2019

iLZR197438185

Violations:

Rule

Violation

Comment

19.15.26 Injection Detection of Deficient Mechanical Integrity Communication with surface

3/18/2019

https://intranetapps.emnrd.state.nm.us/OCD/InspectionsManagement/FieldCompliance/PrintLOV/cLZR197725055

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Hobbs OCD District Office

ck Kickman

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

MAIL SOURCE

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



NEOPOST FIRST-CLASS MAIL S

03/18/2019 ZIP 88240 042L14818194

MACK ENERGY CORP P.O. Box 960 11344 Lovington Hwy Artesia, New Mexico 88211-0960