

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

MAR 18 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name OXY		API Number 30-025-28337 ✓	
Property Name S. Hobbs G/SA		Well No. #133 ✓	

1. Surface Location									
UL - Lot E	Section 3	Township 19S	Range 38E		Feet from 1840	N/S Line N	Feet From 748	E/W Line W	County LEA ✓

Well Status									
TA'D WELL ☒ YES ☐ NO	SHUT-IN ☒ YES ☐ NO	INJ	INJECTOR SWD	PRODUCER ☒ OIL ☐ GAS	DATE 3-18-19 ✓				

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	0	NONE ✓
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	N	Y/N	Y/N	N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

T/A TEST - OK

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS OK	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness: Gary Robinson			

INSTRUCTIONS ON BACK OF THIS FORM