




State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Oil Corp		API Number 30-025-34600	
Property Name North East Drinkard Unit (NEDU)		Well No. 133	

Surface Location

UL - Lot D	Section 2	Township 21S	Range 37E	Feet from 1458	N/S Line N	Feet From 1098	E/W Line E	County Lea
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☒ YES ☐ NO	INJ ☐ INJ ☐ SWD	OIL ☐ OIL ☐ PRODUCER	GAS ☐ GAS	DATE 2-28-19
--	--	--	---	-------------------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	N/A	N/A	N/A	0	0
Flow Characteristics					TA CO2 — WTR — GAS — Type of Fluid Injected for Waterflood if applies
Puff	Y / N	Y / N	Y / N	Y / ☒ N	
Steady Flow	Y / N	Y / N	Y / N	Y / ☒ N	
Surges	Y / N	Y / N	Y / N	Y / ☒ N	
Down to nothing	Y / N	Y / N	Y / N	☒ Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / ☒ N	
Water	Y / N	Y / N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Tracy Cole		OIL CONSERVATION DIVISION	
Printed name: Tracy Cole		Entered into RBDMS	
Title: Pumper		Re-test	
E-mail Address:		K7	
Date: 2-28-19	Phone: 575-445196		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM