District 1 1625 N. French Dr., Hobbs. Phone: (373) 393-434 (2015) 393-0720 WAR 20 2019 State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office BRADENHEAD TEST REPORT

	II.	A DE			HEAD TE	ST RE	PORT					
Mook En	ormi Co		Operator	Operator Name				API Number 30-025-01967				
Mack Energy Corporation								Well No.				
Property Name Miller W State										1	1	
7- Surface Location												
UL-Lot Section Townshi		Township	Range	Feet from		N/S Line		Feet fi	from E/W Line		County	
P 4 175		17S	34E	440		South		44	440 East		Lea, NM	
Well Status												
Well Status			SHUT-IN PRODUCING			DATE						
W CII	Status		Produ		ucing	31		15-19				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUA								Y FOR 1	5 MINUT	TES EACH	-	
				OB	SERVED DA	TA						
If bradehead flowed water, check all of the descriptions that apply:												
		(A)S	urf-Interm	(B)Interm(I)-Interm(2)		(C)Interm-Prod			(D)Prod-Tubing		(E) Tubing	
Pressure			8						15		- 16	
Flow Characteristics											1	
Puff			Y / 🕅	Y/N Y/N		Y / N			. Y / N		-	
Steady Flow			Y / 🕅	Y / N		Y/N			Y/N		-	
Surges			Y / [N]	Y / N		Y/N			Y / N		1	
Down to nothing			Ø / N	Y / N		Y/N			Y/N			
Gas or Oil			Y / 🕅	Y / N		Y / N		Y / N]		
Water			Y / 🔞	Y / N		Y/N		Y/N]		
If bradenhead	flowed wa	ter check al	l of the description	one that annly:								
	nowed wa		_				T					
CLEAR		FRE	ESH	SALTY		SULFUR		BLACK				
Remarks:			. <u> </u>									
remarks.												
Signature:	Signature: July Sund								OIL CONSERVATION DIVISION			
7								Entered into RBDMS				
Printed Name:								Re-test				
Title:								10000				
E-mail Address:								 				
Date: 7-15-19 Phone: 575-748-1288								_/_		<u> </u>		
Witness: Rick Rickman										· · · · · · · · · · · · · · · · · · ·		