District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III District III	t New Mexico and Natural Resources Form C-129 Revised August 1, 2011	
District III 1000 Rio Brazos Road, Aztec, NM 87410 District III 1000 Rio Brazos Road, Aztec, NM 87410 APR 1 5 2019 1220 South Santa F	rvation Division h St. Francis Dr. Submit one copy to appropriate e, NM 87505 District Office	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 RECEIVED	NFO Permit No	
APPLICATION FOR EXCEPTION	TO NO-FLARE RULE 19.15.18.12	
(See Rule 19.15.18.12 NMAC		
A. Applicant ConocoPhillips Company		
whose address is <u>P. O. Box 51810, Midland, TX 79710</u> ,		
hereby requests an exception to Rule 19.15.18.12 fordays or until		
<u>May 14</u> , Yr <u>2019</u> , 1	for the following described tank battery (or LACT):	
Name of Lease <u>VGEU East Battery</u> Name of Pool		
Location of Battery: Unit Letter Section 27 Township 178 Range 35E		
Number of wells producing into battery	31	
B. Based upon oil production of	barrels per day, the estimated * volume	
of gas to be flared is7000	MCF; Valueper day.	
C. Name and location of nearest gas gathering facility:		
D. DistanceEstimated co	ost of connection	
E. This exception is requested for the following reasons: <u>This battery is connecting to a gathering line whi</u> ch		
services multiple operations. Flaring will occur intermittently because the gathering line does not have adequate		
capacity or the pressure from our wells is not enough to overcome the high gathering line pressure. Our		
production is then sporadically curtailed by third party. Attached is a list of wells		
	30 0252072	
OPERATOR I hereby certify that the rules and regulations of the Oil Conservation	OIL CONSERVATION DIVISION	
Division have been complied with and that the information given above is true and complete to the best of my knowledge and belief.	Approved Until 5/14/2019	
Signature Horder By By		
Printed Name	Title Petroleum Engineer	
& Title <u>Rhonda Rogers, Regulatory Technician</u>	Date $O \neq / 1 \neq / 1 q$	
Date 2/14/2019 Telephone No. 432-688-9174 * Gas-Oil ratio test may be required to verify estimated gas verify 432-688-9174 432-688-9174	zolume	

VGEU East Battery	
VG 01-01	30-025-20721
VG 01-02	30-025-20719
VG 01-03	30-025-20715
VG 01-05	30-025-30436
VG 01-06	30-025-30437
VG 01-07	30-025-30805
VG 01-09	30-025-20717
VG 01-14H	30-025-42104
VG 01-17	30-025-37847
VG 04-01	30-025-20856
VG 04-02	30-025-20855
VG 10-03	30-025-20833
VG 11-01	30-025-20624
VG 12-01	30-025-23700
VG 12-02	30-025-20582
VG 12-03H	30-025-42103
VG 22-01	30-025-30506
VG 22-03	30-025-20785
VG 22-04H	30-025-42691
VG 24-02	30-025-20751
VG 24-03	30-025-20752
VG 24-06	30-025-32366
VG 26-02	30-025-21011
VG 26-03	30-025-20882
VG 27-01	30-025-20880
VG 27-05	30-025-02899
VG 27-24	30-025-38210
VG 35-01	30-025-20866
VG 35-03	30-025-20868
VG 42-01	30-025-30505
VG 42-02	30-025-20790
VG 43-01	30-025-20786

total wells

32