

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

APR 24 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chevron Midcontinent, LP	API Number 30-025-02953
Property Name Central Vacuum Unit	Well No 64

Surface Location

U.L. - Lot F	Section 31	Township 17S	Range 130E 35E	Feet from 1980	N/S Line N	Feet from 1980	E/W Line W	County LEA
-----------------	---------------	-----------------	-------------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D Well YES NO	SHUT-IN YES NO	INJECTOR INJ SWD	PRODUCER OIL GAS	DATE 3-28-2019
---------------------	-------------------	---------------------	---------------------	-------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0		300	480
Flow Characteristics					
Puff	(Y) N	(Y) N	Y N	Y N	CO2 _____
Steady Flow	Y (N)	Y (N)	Y N	Y N	WTR _____
Surges	Y (N)	Y (N)	Y N	Y N	GAS _____
Down to nothing	(Y) N	(Y) N	Y N	Y N	If applicable type
Gas or Oil	Y (N)	Y (N)	Y N	Y N	fluid injected for
Water	Y (N)	Y (N)	Y N	Y N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Intermediate had slight water

Signature:	OIL CONSERVATION DIVISION
Printed name	Entered into RBDMS
Title:	Re-test
E-mail Address	
Date:	
Phone	
Witness:	