

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
APR 24 2019
RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-02956
Property Name Central Vacuum Unit	Well No 86

Surface Location

CL - Lot 0	Section 31	Township 17S	Range 3SE	Feet from 660	N/S Line S	Feet From 1980	E/W Line E	County LEA
---------------	---------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

TAD Well YES	SHUT-IN YES	INJECTOR INJ	PRODUCER GAS	DATE 3-28-2019
-----------------	----------------	-----------------	-----------------	-------------------

OBSERVED DATA

	(A) Surf-Intern	(B) Intern(1)	(C) Intern(2)	(D) Prod Csmg	(E) Tubing
Pressure	0			125	550
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Chris Lopez</i>	OIL CONSERVATION DIVISION
Printed name	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	Witness <i>Darryl</i>