

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

APR 24 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chevron Midcontinent, LP	API Number 30-025-02957
Property Name Central Vacuum Unit	Well No 76

Surface Location

U.L. - Lat L	Section 31	Township 17S	Range 35E	Feet from 1980	N/S Line S	Feet from 6600	E/W Line W	County LEA
-----------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------



Well Status

TA'D Well YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR INJ SWD	PRODUCER OIL ☒ GAS	DATE 3-28-2019
--	--	---------------------	--	-------------------

OBSERVED DATA

	(A) Surf-Interm	(B) Interm (1)	(C) Interm (2)	(D) Prod Casing	(E) Tubing
Pressure	0	0		0	150
Flow Characteristics					
Puff	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	CO2 _____
Steady Flow	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	WTR _____
Surges	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	GAS _____
Down to nothing	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	If applicable type
Gas or Oil	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	fluid injected for
Water	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	Water flood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name	Entered into RBDMS
Title:	Re-test 
E-mail Address:	
Date:	Phone
Witness: 