

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OIL
APR 24 2019
RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-25709
Property Name Central Vacuum Unit	Well No. 85

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
L	31	17S	25E	1336	S	1201	W	Lea

Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES ☐ NO ☒	YES ☐ NO ☒	INJ ☒ SWD ☐	OIL ☐ GAS ☐	3-20-19



OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	
Flow Characteristics					
Puff	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☒	CO2 _____
Steady Flow	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☒	WTR _____
Surges	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☒	GAS _____
Down to nothing	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☒	If applicable type
Gas or Oil	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☒	fluid injected for
Water	Y/N ☒	Y/N ☒	Y/N ☐	Y/N ☒	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Need track for prod. csg. fluid.

~~BIRED TO NOTHING~~

Signature: 	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test 
E-mail Address:	
Date:	
Phone:	
Witness: 